PROFORMA REGARDING SAFE DRINKING WATER AND SANITARY CONDITION CERTIFICATE.

	2	
No		Date: 34.01.19
*		Ÿ
•	*	
to be applied that an inconstan	desire beautiful buy	
It is certified that an inspection The Maynut ProRock (Quality M		(Name of Officers
with designation) from Micro Engin	1.1	
Department/Office) inspected the		
on SH-33, Hotheas - Mathera road		
the School) on 1.01.19 and found	that the	
Della Public School Hatwas	(0.0)-204213	(Name of school) has safe
drinking water facilities for the students and	d members of staff o	f the institution and is maintaining
the hygienic sanitation condition in the	school building &	the campus as per the norm
prescribed by the Central/State/U.T Govt.		
The above valid for a period of _a_	months of by	rest service due.
		2 Sanding DV
	Signature with	Seal: NAKE
	Name	: Dusty that Brokent
	Designation	: Quality Manager
Γο	** ,	V.
Delhi Public School Hathers	* * * * * * * * * * * * * * * * * * *	
8 KM Milestone on SH-33 Hatturs		
Nathura road Hathres UP-204213		2
Name & Address of the Institution)		
	SUBLIC SO	<u>^</u>
(Smohan	国行家们首	
`	MUNICIPAL IN	1 Illand